Corner I.D. # 117T

MONUMENT RECORD


STATE OF INDIANA ~ COUNTY OF MONROE

9/1/2016, Rachel Savich Oser, Fbk. 48, pg. 9	Recovery Tie Drawing	
9/4/2018, Cassidy Raley, Fbk. 52, pg. 33		LLLL_
Monument recovered in good condition		
		1 1 1 1
	*** **********************************	
	Shady Pines Picnic Area	
		fjfj-
, c/L		
/ 10/2 N	ain Forest Road	
15.5		12
7		A
• <u>55.5'</u>		//
	Wall's S	/1
/ 2	Wall's Shelterhouse	4
Swing Set	89	ì
	· 2	N
		N.T.S.
		Aluminum Monument
	15-	Aluminum Monument at Corner = •

I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079

COMPLETED BY St. U.Fale





2004 Geodetic Control Project 119 West 7th Street Bloomington, Indiana 47404 (812) 349-2570





